

HORN

HORN BUTTONS

All include black plastic mounting base

50TH ANNIVERSARY

Includes stainless ring, plastic insert and black plastic backing. This button celebrated the Ford trucks 50th year in 1953

Button	2781-53A	\$69.50 ea
Plastic insert only.....	2737-ANV	\$43.50 ea

5 STAR

54-56 polished stainless.....	2785-PS	\$45.00 ea
54-56 black center.....	2784	\$45.00 ea

BOLT & GEAR

Silver with red center.....	2783-56.....	\$49.50 ea
All polished stainless.....	2782-PS.....	\$49.50 ea

Steering wheels see page 151

HORN BUTTON PARTS

CONTACT SPRING	2733	\$6.50 ea
-----------------------------	------------	-----------

Looks like a piece of grapefruit, it is what makes contact with wire

WIRE, INSULATOR & CONTACT	2730.....	\$14.00 ea
--	-----------	------------

Not included in any wire harness, goes inside steering shaft, Bakelite piece is not available separately, is installed on this wire along with special contact end .

BRASS CONTACT CAP	2732	\$6.50 ea
--------------------------------	------------	-----------

This is cap that must be removed to access shaft nut, make sure Bakelite insulator on horn wire is properly seated in center indent

RETAINER BELL SPRING	2734	\$6.50 ea
-----------------------------------	------------	-----------

Slips into slots in cup, makes ears that hold button on, push button down and turn clockwise to install, counter clockwise to remove

SUPPORT CUP	2735.....	\$12.00 ea
--------------------------	-----------	------------

Some buttons have different height cups Measure area between spring slot and top, short one (2735-SHT) is 1/8" and was used in 48-52 trucks and many 57-60 trucks, correct one (2735) is 1/4"

OTHER HORN PARTS

HORN KIT All above pieces.....	92730	\$43.50 kit
---------------------------------------	-------------	-------------

HORN

Replacement, small universal, order by tone.

Low, driver side.....	2793-L.....	\$20.00 ea
High, passenger side.....	2793-R.....	\$20.00 ea

Original snail style. Most trucks had one horn but only sold in pairs

High and low pair.....	2790	\$89.95 pr
------------------------	------------	------------

HORN WIRE From relay to horn.....	3209-H	\$4.50 ea
--	--------------	-----------

HORN MOUNTING BRACKET

1956 driver side.....	2796-56L.....	\$12.50 ea
1956 passenger side.....	2796-56R	\$12.50 ea
1953-55 driver side.....	2795-5355L.....	\$12.50 ea
1953-55 passenger side.....	2795-5355R	\$12.50 ea

HORN BRACKET TO SADDLE BOLTS

Zinc.....	82795-Z.....	\$4.90 ea
Polished hex.....	82795-PX	\$7.90 ea
Polished button.....	82795-PB	\$8.90 ea

HORN TO BRACKET TABS	2798	\$10.00 pr
-----------------------------------	------------	------------

2 pairs needed, this mounts horn to bracket and prevents "dull" sound

HORN BODY TO TAB BOLTS	82798	\$1.10 pr
-------------------------------------	-------------	-----------

BODY TO TAB ATTACHING KIT Original.....	2799	\$4.00 set
--	------------	------------

BODY TO TAB SPACERS Replacements.....	82799	\$1.65 pr
--	-------------	-----------

HORN RELAY

12 volt.....	3229	\$19.95 ea
6 volt.....	6V-3229.....	\$22.50 ea


Note Gm, Ididit & Flaming River Columns use GM Relay, not this one



USA



USA



Yellow/Green
HORNS
Pass. side

Blue/Yellow
HORN BUTTON
Driver side

BATTERY



HORN

1-800-252-1956