


HEATER • DEFROST



DEFROST DEFLECTOR *Oversized shipping*
 1953-55 chrome exchange.....1940-5355 \$100.00 ea
 1956 chrome exchange1940-56 \$110.00 ea
 Core charge for both.....\$50.00 ea
 Screw set polished stainless, 1953-5581940-5355 \$4.00 set
 Screw set polished stainless, 195681940-56 \$4.50 set




DEFROST TUBE
 Plastic Reproductions
 1956 driver or passenger.....1945-56 \$35.00 ea
 1953-55 driver, deeper one1945-5355L \$29.95 ea
 1953-55 passenger, shorter one.....1945-5355R..... \$29.95 ea
 Defrost tube seal1943.....\$3.00 pr
 Defrost tube attaching hardware
Threaded studs are pressed into 53-55 dash, use 56 for 53-55 dash with missing studs.
 1953-5581947-5355 \$2.00 ea
 1956.....81947-56 \$4.00 set




DEFROST HOSE
 Hose, pair (6 ft). Note size of heater outlets and defrost tubes
 1953-55, 2" diameter1928-5355 \$22.00 pr
 1956, 2 1/2" diameter1928-56 \$22.00 pr
 Defrost hose adapter, 2" to 2 1/2".....1952..... \$4.25 ea
Use to adapt 1953 heater to 56 truck and visa versa or a/c defrost hose to defrost tubes. Also aftermarket a/c units are 2"
 Defrost hose clamp
 All stainless.....1616-SS..... \$3.00 ea
 Polished stainless, show quality.....1616-PS..... \$5.50 ea



FRESH AIR DUCT
See page 108 for cab repair panels with louvers
 Louver removal patch panel1903..... \$20.00 ea
Curved to match cowl, and flanged for easy installation
 Air intake cowl screws, polished81939..... \$4.00 set
Shows on outside of cab
 Fresh air duct, plastic reproduction1939..... \$65.00 ea
New abs reproduction, scoops fresh air into heater.
 Vinyl boot, black1936..... \$9.50 ea
 Fresh air duct gasket1937..... \$6.75 ea
 Fresh air duct cover.....1938..... \$29.95 ea
New, made of black abs plastic, covers vent louvers from inside.



HEATER TUBE FIREWALL SEAL ..1930..... \$4.90 pr
HEATER SEAL KIT.....1904..... \$13.50 set
Includes 2 core seals & 1 Motor seal



HEATER CORE
Rebuilt with new core. Heater cores have different tube designs. Note your style A, B, C or D. If in doubt send your core to us for rebuilding. Heaters are not the same in different years but can be interchanged with little problem, note defrost hose adapter and identification notes above.
 Tubes, 1 straight and 1 angled1935-A..... \$168.50 ea
 Tubes, both angled.....1935-B..... \$168.50 ea
 Tubes, one angled more than other1935-C..... \$168.50 ea
 Tubes, both angled backwards.....1935-D..... \$168.50 ea
 Sold exchange, core charge for all above cores \$50.00 ea
 Copper tubes.....1931..... \$20.00 ea
We make so we can rebuild cores, in copper, so very expensive, included in our cores above
 Note drawings are with the core toward you, and tubes away from you, pointing up

