


DOOR & WINDOW PARTS

DOOR HANDLE REGULATOR

Send in old ones if you are not using for \$5.00 each.



REGULATOR

- Stock length..... 1090 \$45.00 ea
- 1/4" longer shaft..... 1090-L \$59.00 ea

REGULATOR SCREWS Does both sides



- Zinc..... 81090-Z \$2.50 set
- Stainless..... 81090-SS \$3.50 set
- Polished stainless..... 81090-PS \$5.00 set

REPAIR SHAFT

- Stock length..... 1100 \$17.50 ea
- 1/4" longer shaft for thick upholstery 1101-L..... \$19.50 ea

Requires tack welding to reassemble, 2 springs and tiny plunger may escape when disassembled, be careful, they are not available.

WINDOW REGULATORS

Some on market are bad, window falls, these are correct. All regulators with longer shafts to clear upholstery are rebuilt only. Power regulators available, see page 94



REGULATOR

- 1953-55 driver, stock shaft 1105-5355L..... \$89.00 ea
- 1953-55 passenger, stock shaft 1105-5355R..... \$89.00 ea
- 1953-55 driver, 1/4" longer shaft..... 91103-5355L... \$99.00 ea
- 1953-55 passenger, 1/4" longer shaft..... 91103-5355R... \$99.00 ea
- 1956 driver, stock shaft..... 1106-56L..... \$89.00 ea
- 1956 passenger, stock shaft..... 1106-56R \$89.00 ea
- 1956 driver, 1/4" longer shaft..... 91104-56L..... \$99.00 ea
- 1956 passenger, 1/4" longer shaft..... 91104-56R..... \$99.00 ea

CAPTIVE NUT

WINDOW REGULATOR SCREWS Does both sides

- Zinc..... 81151-Z \$3.50 set
- Stainless..... 81151-SS..... \$5.50 set
- Polished stainless..... 81151-PS..... \$6.90 set

REPAIR SHAFT With instructions


- 1953-55 stock length 1102-5355 \$17.50 ea
- 1953-55 1/4" longer shaft 1103-5355L..... \$19.50 ea
- 1956 stock length 1102-56 \$17.50 ea
- 1956 1/4" longer shaft..... 1103-56L..... \$19.50 ea

INNER REPAIR SPRING This is the piece that most often breaks

- 1953-55 1103-SP5355..... \$5.50 ea
- 1956..... 1103-SP56..... \$6.25 ea

LOWER GLASS LIFT CHANNEL

The smooth side goes toward outside of door. Install roller in channel from end, having trouble with steel rollers? May be too thick, use nylon rollers below



CHANNEL

- 1953-55 1118-5355..... \$28.50 ea
- 1956 driver..... 1118-56L..... \$25.00 ea
- 1956 passenger..... 1118-56R \$25.00 ea

GLASS SEAT TAPE KIT

- Does both sides..... 81620 \$5.00 pr

WINDOW GLASS ROLLER 1956-1 per door, 1953-55-2 per door

- Nylon 1116 \$3.95 ea

You do not want steel, it was original, but anything on the market in last few years must be modified to work.

