



DOOR REPAIR PANELS



WINDOW SILL STRAIGHTENER STRIPS



Straighten lower window openings for repair or flat glass solid windows on a 53-55, set of inner and outer for each door, 4 pieces, with clip slots. Fits entire lower edge of window opening, if using with vents, cut at division bar.

Set of 43113-4\$39.95 set

DOOR SHELL

Nice reproduction, complete inner & outer skin, no inner workings, inspection plates or handles. Ships freight, call for quote. 1956 In the works, but on back burner, so doubtful.

1953-55 driver7795-5355L ...\$450.00 ea
 1953-55 passenger.....7795-5355R...\$450.00 ea



DOOR INSPECTION PLATE

Always use behind door panels to reduce noise & protect upholstered panels from indirect moisture. Inspection plate modifications, see page 12

ABS, nice, easy to work with2126-ABS\$47.50 ea
 Steel2126-STL.....\$47.50 ea
 Inspection plate gasket.....2126-GSKT \$19.95 pr
 Inspection plate screw sets
 Zinc81118-Z \$3.50 kit
 Stainless81118-SS \$6.90 kit
 Polished stainless.....81118-PS \$10.50 kit

USA



DOOR DAMPENERS KITS

Strips of self adhesive material to reduce noise and vibration

Inner door does both92180\$25.00 kit
 Outer door, behind upholstered panel .92181 \$25.00 kit

USA



DOOR HINGE COVER PLATE

Regular1178\$8.50 ea
 Oversize, for China panel1177\$8.50 ea

Retainer strip location
 A..11/16" to 7/8" from inside edge
 B..1 3/4" bottom edge of door
 C..2" from back hinge side of door
 D..3" from front side of door



USA

DOOR SEAL LOWER RETAINER STRIP

1953-567727\$4.50 ea

LOWER INNER DOOR BOTTOM PANEL

18 gauge steel replacement panels, not a cover. TALL goes up above hinge inspection hole. China made but is nice, little better than USA made above. Oversize shipping


Short ,driver 7"7725-L\$45.00 ea
 Short, passenger 7"7725-R.....\$45.00 ea
 Tall, driver 9"7726-L\$45.00 ea
 Tall, passenger 9"7726-R.....\$45.00 ea



LOWER OUTER DOOR PANEL

About 10 3/4" tall, black electro primer , oversize shipping

Driver7724-L\$40.00 ea
 Passenger7724-R.....\$40.00 ea
 USA driver, raw steel7723-L\$60.00 ea
 USA passenger, raw steel7723-R.....\$60.00 ea



Insulate inside of door and between interior panels see page 24. Don't forget to drill drain holes in bottom after replacing patch panels

