

**STRIKER PLATE SAFETY COVERS**  
**#@\$!\*@#\$\$% INSTRUCTIONS**  
**MID FIFTY F-100 PARTS 1-800-252-1956**

PART NUMBER

**1112**

Striker plate safety covers were original equipment on 1956.  
They are intended to capture the latch star to help keep the door shut in an emergency.  
To install on 1953-55, use 1956 star latches. Everything else is the same.  
Sy was not consulted by manufacturing so the mounting threads are wrong, we include the correct screws

031405