

1956 Wiper Linkage & Parking

INST-3000-56

3004-56


3023

3030


PAGE 1 OF 1

#@\$!*@#\$\$% INSTRUCTIONS
MID FIFTY F-100 PARTS 1-800-252-1956

1956 WIPER & LINKAGE ASSEMBLY




Do not run motor with Arm & Blade attached to pivots Without adjusting park feature first




Wiper arms may hit cowl, damaging paint, arms and motor.
Determine proper park location: Running motor, Without Arm & Blade Assembly attached.
Stop, let park,
Mark location on pivot, test a few times, make sure it is parking in same place each time.
Make sure it is not going down before sweeping upward as shown to left.
When you are positive both pivots are turning correctly.
Then attach blade & arm assembly.

PARKING INSTRUCTIONS



Clevis can be adjusted by lifting away from motor knurls and turning slightly.



Motor is under hood, this view is looking under the dash where actually all that is seen would be the motor post and clevis.

120803, 121504, 071106

