

#@\$%# INSTRUCTIONS

MID FIFTY F-100 PARTS

800-252-1956

midfifty.com

Article written during installation of kit at BobCo few years back. Since then we have improved the power window kit by including a reinforcing piece. Power window manufacture went from steel corner to plastic which we found to be insufficient and prone to breakage. They would not fix so we made a reinforcement plate, not shown in this article.

To read the article please copy and paste the following link in your internet browser, google, etc.

<https://www.hotrod.com/articles/installing-f-100-mid-fifty-power-windows/>

<https://www.hotrod.com/articles/installing-f-100-mid-fifty-power-windows/>