


USA

CAB REPAIR PIECES



USA



USA



USA



USA



USA



additional shipping on any dash repair .ADD \$15.00 ea

..... **1956 FIBERGLASS DASH**6509 \$275.00
 very nice well made fiberglass, from seam to seam, does not include glove box door but accepts original, does not have ash tray or provision for ash tray, accepts any 56 instrument cluster. Ships UPS additional \$20.00.

.... **1956 DASH REPAIR** Rolled bottom edge and flanges for ease of installation, 18 gauge steel Seam to Seam , covers glove box area7535\$59.00

..... **1953-55 DASH REPAIR**, correct curves, can go over existing dash or replace it, goes to horizontal seam and door to door, removes glove box & ash tray.7536-5355 ..\$125.00

DASH EXTENSIONS, STEEL Angled out from dash at almost 45 degrees, 4" deep, will hold most anything.

• **ANGLED** Bottom with column opening .7533\$79.00

• **ROUNDED** bottom no opening7532\$99.95

..... **ROUNDED** bottom with column hole and support 2" column hole & support7540-2 ..\$165.00

..... 2.25" column hole & support7540-25 ..\$165.00

..... slice of dash extension shown so you can see the nice rounded bottom. Ends filled in and finished, not shown here.

X-TEND-A-DASH, ABS & FIBERGLASS molded to fit contour of dash, adds 3 inches to bottom, allows glove box door to open. Will hold Vintage Air Oval panel, Gauges, Air ride switches, etc.

• **Fiberglass**7530\$136.50

• **ABS Black, paintable, easy to modify** ..7531\$136.50

FRONT CAB BODY MOUNT BRACKET

DRIVER7718-L\$26.50 ea.

PASSENGER7718-R\$26.50 ea.

INNER FENDER TO LOWER CAB MOUNTING ANGLE, interchangeable. 56 short, longer 53-55 style fits 56 as well

DRIVER, 1953-55, will fit all1564-5355L\$22.50 ea.

PASSENGER, 1953-55, will fit all1564-5355R\$22.50 ea.

DRIVER, 1956, will fit all1564-L\$22.50 ea.

PASSENGER, 1956, will fit all1564-R\$22.50 ea.

FRONT FENDER UPPER MOUNTING BRACKET Common rust area, or if bent will cause hood & fender alignment problems.

DRIVER1563-L\$22.50 ea.

PASSENGER1563-R\$22.50 ea.

Call with any concerns about reproduction panels from China, some good, some not so good.

COMPLETE FRONT CAB CORNER & COWL

Goes all the way to upper seam, includes hood hinge area.

Nice piece, best one for door edge area, *Oversize shipping.*

COWL, to seam, Driver7705-L\$55.00 ea.

COWL, to seam, Pass, With LOUVERS7705-FA ..\$65.00 ea.

COWL, to seam, Pass., NO louvers7705-R\$58.50 ea.

FRONT COWL & FENDER REINFORCEMENT

Piece on inside of cab that fender bolts through, includes fender locating nut, this is where to start aligning fenders, rust or fatigue here may cause misalignment. good piece

Order L or R1562-(L or R) ...\$20.00 ea.

LOWER FRONT CAB CORNER, China made

Order Left or Right7711-22(L or R) ..\$50.00 ea.

Sy's 13" USA made7710-13(L or R) ..\$50.00 ea.

FRONT LOWER INSPECTION PLATE use on some 55's, all 56's and all new panels with holes7712\$16.50 pr

INSPECTION PLATE SCREWS87712\$1.50 set

FRONT LOWER DOOR PILLAR


WITH HINGE BUCKET, DRIVER7713-L\$42.50 ea.

WITH HINGE BUCKET, PASS7713-R\$42.50 ea.

NO HINGE BUCKET, DRIVER7714-L\$39.00 ea.

NO HINGE BUCKET, PASS7714-R\$39.00 ea.

REAR DOOR PILLAR, shown pg 114 ..7715-L or R ..\$39.00 ea.



**DASH REPAIR
 CAB REPAIR**