NO Not to be an 8 1/2"

original 8 1/2" this one 5 1/2"

ANEL TRUCK

No mounting holes for brackets, must be drilled, or glued to brackets. Worth it, makes nice neat bright polished bumper.

••PANEL TRUCK REAR BUMPER BRACKETS, highly polished beautiful pieces, set of 4P-0604-PL\$259.00 set

MID FIFTY F-100 PARTS midfifty.com