


DASH TRIM & RADIO



1956 Defrost Deflectors are hard to find these days, die to do them is way to expensive, I am thinking of making them in chrome plastic, what do you think?

DASH & DOOR INTERIOR CUSTOM CAB TRIM, 1953-55

All 4 pieces with clips1216 \$60.00 set
if you have tiny holes in door and across dash this is what was there

DASH & DOOR MOULDING CLIP tiny clips, takes 20 to do all 4 pieces
One individual clip81217-1 \$.60 ea.
SET OF 2081217-20 \$9.50 set

DEFROST DEFLECTOR, goes across dash at windshield. Ship core to us taped to a piece of wood, can be damaged very easily, will be unchromeable and unusable. If damaged no core charge refunded.

1953-55 CHROME EXCHANGE1940-5355 \$100.00 ea.
1956 CHROME EXCHANGE1940-56 \$110.00 ea.
CORE CHARGE.....53-55...\$50.00 1956..... \$75.00
Additional Shipping ChargeADD \$20.00 ea.


DEFROST DEFLECTOR SCREW SET, POLISHED STAINLESS

1953-5581940-5355 \$4.00 set
195681940-56 \$4.50 set

DASHES and DASH REPAIR PIECES see page 114 & 170



1956
1953-55



ORIGINAL RADIO PIECES

NEW



SPEAKER, fits original location and mounting holes, Quality in correct size, and affordable.0185 \$28.50 ea.

SPEAKER INSTALL BOLTS, 1954-5580177-5 \$3.90 set

SPEAKER WING NUTS, 1953-5680178-5356 \$3.90 set



NEW

SPEAKER GRILLE SCREEN0184 \$8.00 ea.

SPEAKER COVERS, Fiberglass, not the real thing but a very nicely made fiberglass copy

Grey, 53-55 (horizonatl bars)0179-5355 \$88.00 ea.

Grey, 1956 (vertical bars)0179-56 \$88.00 ea.

SOME USED RADIOS AVAILABLE, AS IS may or may not work, Can be rebuilt to AM/FM does not include knobs. Note: Knobs can be interchanged, only difference was in looks of clear plastic and black number plate. Original speaker was located in center above mirror

6V to 12V CONVERTER, will run 12 volt radio on 6 volt system, good for LED lights, accessories, etc.2923 \$69.95 ea.

ELECTRONIC ANTENNA, Excellent reception, completely concealed. NO external mast means no drilling, no damage, no vandalism.

Install as close to glass as possible, self stick. 3 1/2" X 3/4"

Long Cable, 9 ft0177-A1 \$49.95 ea.

Short Cable, 6 ft0177-A2 \$49.95 ea.

ADD ON SIDE ANTENNA, not stock but popular 50's add-on. Perfect high quality repo, has correct Retro-Red ball on top, not cheaper knock-off. Includes lead wire0178 \$39.95 ea.

Cheaper knock-off, no red ball0178-EC \$24.95 ea.

RADIO TRIM RING, Polished Aluminum replacement, not original but looks perfect. Hand made.0171-PA \$75.00 ea.

RADIO KNOBS, stock styles, Sy is working on, get on first-serve list, see page 3 or our website

RADIO INSTALL SCREWS80170 \$3.90 set

RADIO MAST ASSEMBLY ONLY0176 \$20.00 ea.


RADIO ANTENNA, Hole is 1 1/8" at angle on cowl, Complete exact of original reproduction assembly, includes instructions.

1953-550175-5355 \$65.00 ea.

19560175-56 \$65.00 ea.

RADIO MANUAL 53-55 With Template ...B-11169 \$3.50 ea.

No longer available, but have ONE we will copy for you. 11 pages, charge is just for paper, printing again soon.



RED BALL

Installs on
Passenger side



**RADIO
DASH REPAIR**

1-800-252-1956