



DOOR REPAIR PANELS



WINDOW SILL STRAIGHTENER STRIPS


Straighten lower window openings for repair or flat glass solid windows on a 53-55, set of inner and outer for each door, 4 pieces, with clip slots. Fits entire lower edge of window opening, if using with vents, cut at division bar.

Set of 4	3113-4	\$39.95 set
One, Outer R, Inner L	3113-R	\$12.00 ea
One, Outer L, Inner R	3113-L	\$12.00 ea

DOOR SHELL

Nice reproduction, complete inner & outer skin, no inner workings, inspection plates or handles. Ships freight, call for quote. 1956 In the works, but on back burner, so doubtful.

1953-55 driver	7795-5355L	\$450.00 ea
1953-55 passenger	7795-5355R	\$450.00 ea



DOOR INSPECTION PLATE

Always use behind door panels to reduce noise & protect upholstered panels from indirect moisture. Inspection plate modifications, see page 13


ABS, nice, easy to work with	2126-ABS	\$49.00 ea
Steel	2126-STL	\$47.50 ea
Inspection plate gasket	2126-GSKT	\$19.95 pr
Inspection plate screw sets		
Zinc	81118-Z	\$3.50 kit
Stainless	81118-SS	\$6.90 kit
Polished stainless	81118-PS	\$10.50 kit



DOOR DAMPENERS KITS

Strips of self adhesive material to reduce noise and vibration

Inner door does both	92180	\$25.00 kit
Outer door, behind upholstered panel	92181	\$25.00 kit



DOOR HINGE COVER PLATE

Regular	1178	\$8.50 ea
Oversize, for China panel	1177	\$8.50 ea

Retainer strip location
 A..11/16" to 7/8" from inside edge
 B..1 3/4" bottom edge of door
 C..2" from back hinge side of door
 D..3" from front side of door



DOOR SEAL LOWER RETAINER STRIP

1953-56	7727	\$4.50 ea
---------------	------------	-----------

LOWER INNER DOOR BOTTOM PANEL

18 gauge steel replacement panels, not a cover. TALL goes up above hinge inspection hole. China made but is nice, little better than USA made above. Oversize shipping


Short, driver 7"	7725-L	\$45.00 ea
Short, passenger 7"	7725-R	\$45.00 ea
Tall, driver 9"	7726-L	\$45.00 ea
Tall, passenger 9"	7726-R	\$45.00 ea



LOWER OUTER DOOR PANEL

About 10 3/4" tall, black electro primer, oversize shipping

Driver	7724-L	\$40.00 ea
Passenger	7724-R	\$40.00 ea
USA driver, raw steel	7723-L	\$69.95 ea
USA passenger, raw steel	7723-R	\$69.95 ea



Insulate inside of door and between interior panels see page 24. Don't forget to drill drain holes in bottom after replacing patch panels

