

VENT WINDOW



VENT GLASS *Clear, tint, smoke, double dark or (blue add \$1.00 ea)*
 1953-55, choose color.....1700-5355 \$22.00 ea
 1956, choose color1700-56 \$22.00 ea
 Vent glass seat tape, both sides.....81619-V \$5.00 pr

1953-55 VENT FRAME ASSEMBLY

Polished stainless, very nice polished stainless reproductions, include upper pivot cup, lower pivot stem, handle bracket & shaft.

1953-55 left1149-L \$99.00 ea
 1953-55 right1149-R \$99.00 ea

1956 VENT FRAME, CHROME ORIGINALS Call

VENT FRAME SCREWS

Screw set.....81145..... \$2.50 set
 Counter-sunk washers.....81145-W \$0.65 set

VENT WINDOW RUBBER SEALS

1956.....3123-56 \$69.85 pr
 1953-553123-5355 \$69.85 pr
 Economy, old stock, 56 Only left3122-56 \$30.00 pr
Rubber quality not quite as good but works, old stock from early 80's

VENT RUBBER PROTECTOR RIVET ..81143..... \$2.00 kit

Screw and special brass insert that protects 1953-55 rubber. You need these with new rubbers for correct installation.

VENT WINDOW HANDLE

1953-55 Driver...1140-5355L or Passenger..1140-5355R \$26.50 ea
 1956 Driver....1141-56Lor... Passenger..1141-56R..1141-56L\$29.99 ea

VENT HANDLE BUTTON KIT Kit.....1148..... \$5.00 kit

Chrome button, spring, washer, pin, does one handle. Got your buttons elsewhere with the wrong washer?, That'll teach ya.

Correct washers81146..... \$2.50 pr
 Handle retaining pin81141..... \$0.75 pr

VENT HANDLE STRIKER PLATE

1956 doesn't use striker plate, uses division bar

1953-551142-SP \$16.50 ea

VENT HANDLE BRACKET & POST ASSEMBLY

1953-55 plain stainless.....1144-5355..... \$15.00 ea
 1953-55 Polished stainless, pair1143-5355PS..... \$42.50 pr
 1953-55 Polished stainless, One.....1143-5355PS-1.. \$25.00 ea
 1956 plain stock, right, passenger.....1144-56R \$15.00 ea
 1956 plain stock, left, driver.....1144-56L \$15.00 ea
 1956 chrome, commercial chrome, not ours1142-56CH \$32.50 pr
 1956 polished stainless, right1143-56PSR \$25.00 ea
 1956 polished stainless, left1143-56PSL..... \$25.00 ea

RIVET AND INSTALLATION TOOL KIT *Includes tool & 3 sizes rivets for upper & lower vent frame pivots, upper cups, handle brackets, & division bar, 40 in all*81148..... \$17.25 kit

RIVET PACK (40).....81147 \$9.00 set

1953-55 UPPER PIVOT POST

Driver...1146-ML Passenger...1146-MR..... \$15.00 ea

1953-55 VENT FRAME UPPER PIVOT CUP

Driver....1146-CL Passenger...1146-CR \$20.00 ea

VENT FRAME LOWER PIVOT

1956 post only1145-56..... \$20.00 ea
 1956 pivot lower nylon bushing1145-56PB..... \$4.00 ea
 1953-55 post only.....Driver..1145-L...Passenger...1145-R..... \$12.00 ea
 1953-55 pivot spring & washer set1145-SPNG \$14.00 kit
 1953-55 Spring only1145-SP \$12.00 ea
 1953-55 teardrop washer only.....1145-WT \$4.50 ea
 1953-55 assembly, Driver.....1147-L \$24.00 ea
 Passenger1147-R \$24.00 ea

New reproduction, exact of original, includes proper stop washer, locating knurls, tension washers and spring to keep vent from flopping in the wind.