

5500

1964-66 Instrument panel without gauges

1. Oil light
2. Gas gauge
3. Right hand turn signal
4. Dash lights
5. Temperature hot
6. Temperature cold
7. Generator light
8. High beam
9. Left hand turn signal

